

MEM30305-WT77 Cert III in Engineering Fab (Heavy/Welding YH)

Dress requirements / PPE

- Enclosed steel capped safety boots - Heavy leather uppers and heavy-duty soles
- Long heavy cotton drill trousers and cotton drill shirt
- Safety glasses MUST be clear and meet Australian Safety Standards - No sunglasses are permitted in the workshop
- Hearing protection supplied, must be worn in designated areas, as per safe operating procedures.
- Disposable earplugs, gloves and dust masks will be supplied, where required.
- Long hair must be tied-up or contained

Recommended

- Welding helmet
- Welding gloves
- TIG gloves
- Riggers gloves

Stationery requirements

- 1 x A4 2-ring lever arch file
- A4 Lined paper/notebook
- Pens / Pencils / Eraser / Pencil sharpener
- 2H/H Pencils
- USB
- Compass set (talk to lecturer first for details)
- Steel ruler
- 45 degree set square
- 30/60 degree set square
- Scientific calculator

Textbooks

Will be supplied in electronic format