

CPC32011 Certificate III in Carpentry & Joinery

Dress requirements / PPE

- Enclosed steel capped safety boots - Heavy leather uppers and heavy-duty soles
- Long heavy cotton drill trousers and cotton drill shirt (short sleeves allowed)
- Safety glasses MUST be clear and meet Australian Safety Standards - No sunglasses are permitted in the workshop
- Wide brim hat & sunscreen for outside work.
- Hearing protection provided must be worn in designated areas, as per safe operating procedures.
- Disposable earplugs, gloves and dust masks will be supplied, where required.
- Long hair must be tied-up or contained

Stationery requirements

- 1 x A4 2-ring lever arch file
- USB Flash Drive - 8GB
- 1pkt A4 Reinforced loose paper (100 pack)
- 1 Calculator (basic model but have square root function)
- 2 red & 2 blue pens
- 2 HB pencils
- 1 Eraser
- 1 scale rule (with scales 1:1 - 1:5 1:10 - 1:100 1:20 - 1:200 1:50 - 1:500)
- 1 set squares & protractor (45° set square)

Other requirements

Minimum licence requirement/competency is a white card (CPCCWHS1001 Prepare to Work Safely in the Construction Industry)

Textbooks

This will be discussed further on your first day of TAFE.

Texts can be ordered from Albany Learning Resource Centre Bookshop T | 6371 3860 E | Bookshop.GS@srtafe.wa.edu.au