

## **MEM30205-WT83-CERTIFICATE III IN ENGINEERING - MECHANICAL TRADE (FITTER AND MACHINIST ZB)**

## **MEM30205-WT86-CERTIFICATE III IN ENGINEERING - MECHANICAL TRADE (MECHANICAL FITTER ZA)**

### **Dress requirements / PPE**

- Enclosed steel capped safety boots - Heavy leather uppers and heavy-duty soles
- Long heavy cotton drill trousers and cotton drill shirt
- Safety glasses MUST be clear and meet Australian Safety Standards - No sunglasses are permitted in the workshop
- Hearing protection supplied, must be worn in designated areas, as per safe operating procedures.
- Disposable earplugs, gloves and dust masks will be supplied, where required.
- Long hair must be tied-up or contained

### **Stationery requirements**

- 1 x A4 2-ring lever arch file
- A4 Lined paper/notebook
- Pens / Pencils / Eraser / Pencil sharpener
- 2H/H Pencils
- USB
- Compass set
- Steel ruler
- 45 degree set square
- 30/60 degree set square

### **Textbooks**

Will be discussed on your first day of TAFE.

Texts can be ordered from Albany Learning Resource Centre Bookshop T | 6371 3860 E | [Bookshop.GS@srtafe.wa.edu.au](mailto:Bookshop.GS@srtafe.wa.edu.au)